Message

From: John.Stroiazzo@glencore-ca.com [John.Stroiazzo@glencore-ca.com]

Sent: 6/5/2017 6:22:09 PM

To: mritorto@rouxinc.com; Cirian, Mike [Cirian.Mike@epa.gov]

CC: swright@cfaluminum.com

Subject: FW: Ramps into the cell lines - begin removing basement concrete - some pictures of concrete with rebar removed -

(painted)

Attachments: FW: Placement area for the concrete from pot rooms 1 - 4; dirt ramp placement area..jpg; Borrow pit mateiral for

ramps.jpg; rebar from concrete picture.jpg; sized concrete picture.jpg

FYI

Calbag is keeping MDEQ notified of their plans.

John

From: Cliff Boyd [mailto:cliff.boyd@calbag.com]

Sent: June-05-17 2:18 PM

To: Stroiazzo, John (Toronto - CA) < John. Stroiazzo@glencore-ca.com>; Steve Wright (swright@cfaluminum.com)

<swright@cfaluminum.com>

Subject: FW: Ramps into the cell lines - begin removing basement concrete - some pictures of concrete with rebar

removed - (painted)

John

Per our conversation this morning, Calbag sent MDEQ the attached email.

Cliff Boyd
Director of Asset Recovery
U.S Operations Group
Oregon Office 503-226-3441
Cell 406 360-0751

From: Cliff Boyd

Sent: Monday, June 05, 2017 12:14 PM

To: 'Mikita, Cory'; Rieger, Michael; 'kathryn.norris@tetratech.com'

Subject: Ramps into the cell lines - begin removing basement concrete - some pictures of concrete with rebar removed - (nainted)

(painted)

Cory and Mike

The west rectifier has been removed opening the area where I will bring down clean fill from the borrow pit to build the ramps. Once the ramps are in, I will begin to remove the basement concrete, move it to the north side of the property for future removal of the rebar and crushing.

- 1) Email attachment where CFAC instructed Calbag to place the material for future rebar removal and crushing. Wells were located so we would not cover them or hit them.
- 2) Dirt ramp placement photo shows the floor that needs to be removed to make access for the dirt ramp. Ramp will run from about the excavator is sitting to the ledge you see in the picture.
- 3) Borrow pit material picture is the open cut mine located about ½ mile from the cell lines.

- 4) We processed some rebar out of the painted concrete from the West Rectifier. Sample picture of what the rebar will look like before it's sheared to mill size
- 5) Size concrete is what the material will look like after the rebar has been taken out. This material is also from the painted walls in the West Rectifier.

I would estimate we will start removing the basement concrete on or about June 12th. Please contact me if you have any questions,

Regards,

Cliff Boyd Director of Asset Recovery U.S Operations Group Oregon Office 503-226-3441 Cell 406 360-0751

LEGAL DISCLAIMER. The contents of this electronic communication and any attached documents are strictly confidential and they may not be used or disclosed by someone who is not a named recipient.

If you have received this electronic communication in error please notify the sender by replying to this electronic communication inserting the word "misdirected" as the subject and delete this communication from your system.

MENTION LEGALE: Le contenu de cette communication électronique et ses pièces jointes sont strictement confidentiels et ne peuvent pas être utilisés ou divulgués par une personne qui n'est pas le destinataire désigné.

Si vous avez reçu cette communication électronique par erreur, s'il vous plaît, veuillez aviser l'expéditeur en répondant à cette communication électronique en insérant le mot 'mauvais destinataire' dans le sujet et supprimer ce message de votre système informatique.